


Appendix H.1 Site Photo Record of Final Inspection for EPSS4 **BH10** (1,500L Above-ground Fuel Tank)




BH10 View 1 – concrete floor condition underneath 1,500L Above-ground Fuel Tank




BH10 View 2 - drip tray condition of the 1,500L Above-ground Fuel Tank

Appendix H.2 Site Photo Record of Final Inspection for EPSS4 **HS2** (Emergency Generator connected to 1,500L **Above-ground Fuel Tank (BH10)**)

Generator HS2 (Stand on 200mm-thick concrete plinth)



HS2 View 1 - concrete floor condition underneath emergency generator



HS2 View 2 - concrete floor condition underneath emergency generator



HS2 View 3 - concrete floor condition underneath emergency generator