

Appendix D. Monitoring Schedule



Monitoring Schedule of This Reporting Period

Jul-16

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday		
					1	2		
3	4	5 NM1A/AR1A NM4 NM6	6 NM5/AR2 NM3A Site Inspection	7	8	9		
10	11 NM1A/AR1A NM4 NM6	12 NM5/AR2 NM3A	13	14 Site Inspection	15 AR1A	16		
17	18 NM5/AR2 NM3A	19	20 Site Inspection	21 NM1A/AR1A NM4 NM6	22 AR2	23		
24	25	26	27 NM1A/AR1A NM4 NM6 Site Inspection	28 NM5/AR2 NM3A	29	30		
31		Notes: Air quality and Noise montiorng Station	NM1A/AR1A - Man Tung Road Park NM3A - Site Office NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan					



Tentative Monitoring Schedule of Next Reporting Period

Aug-16

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday			
	1	2	3	4	5	6			
		Z	-	-	5	0			
			Site Inspection						
					NM6				
		AR1A	NM5/AR2		INIVIO				
			NM3A		CWD Vessel Survey				
	CWD Land-based Survey		NM1A/ AR1A		CWD Land-based Survey				
	CVVD Land-based Survey	WQ General & Regular DCM	NM1A/ AKTA	WQ General & Regular DCM	CWD Land-based Survey	WQ General & Regular DCM			
					11.01				
				mid- ebb:	14:04	mid- ebb: 15:16			
		mid- flood: 19:4		mid- flood:	20:53	mid- flood: 08:36			
7	8	9	10	11	12	13			
			Site Inspection						
	NM1A/AR1A	NM5/AR2			AR1A				
	NM4	NM3A							
	NM6								
		CWD Vessel Survey							
	CWD Land-based Survey	CWD Land-based Survey	CWD Vessel Survey	CWD Vessel Survey	CWD Vessel Survey				
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM			
		mid- ebb: 16:	56	mid- ebb:	18:46	mid- ebb: 09:19			
		mid- flood: 10:4		mid- flood:	13:12	mid- flood: 16:47			
2.4	15								
14	15	16	17	18	19	20			
	1115/100		Site Inspection						
	NM5/AR2			NM1A/AR1A	AR2				
	NM3A			NM4					
				NM6					
	014/53/		CWD Vessel Survey						
	CWD Vessel Survey	CWD Vessel Survey	CWD Land-based Survey						
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM			
		mid- ebb: 11:4		mid- ebb:	12:59	mid- ebb: 14:16			
		mid- flood: 18:4	48	mid- flood:	19:52	mid- flood: 07:45			
21	22	23	24	25	26	27			
21	22	25		25	20	21			
			Site Inspection						
			NM1A/AR1A	NM5/AR2					
			NM4	NM3A					
			NM6	Ecological Monitoring at Sha Cha	u				
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM			
		mid- ebb: 16:2	22	mid- ebb:	18:25	mid- ebb: 08:51			
		mid- flood: 10:		mid- flood:	12:51	mid-flood: 16:13			
	0.0				12.01	10.10			
28	29	30	31						
			Site Inspection						
		NM1A/AR1A	NM5/AR2						
		NM4	NM3						
		NM6	ININIS						
		WQ General & Regular DCM							
		mid- ebb: 11:4							
		mid- flood: 18:4	42						
		Notes:							
			NM1A/AR1A - Man Tung Road Park						
			NM3A - Site Office						
		Air quality and Noise montiorng Station	NM4 - Ching Chung Hau Po Woon Primary	y School					
			NM5/AR2 - Village House, Tin Sum						
			NM6 - House No. 1, Sha Lo Wan						
		CWD - Chinese White Dolphin	×						
		WQ - Water Quality							
		DCM - Deep Cemenet Mixing							
		Dow - Deep Cemener wixing							