Appendix B. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Jul-19

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday		
	1	2	3	4	5	6		
		Site Inspection	Site Inspection	Site Inspection	Site Inspection			
		AR1A	AR2*					
		NM1A, NM4, NM6	NM5					
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM		
		mid-ebb: 12:41 mid-flood: 05:39		mid-ebb: 14:09 mid-flood: 07:05		mid-ebb: 15:44 mid-flood: 08:41		
7	8	9	10	11	12	13		
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection			
	CWD Survey (Vessel) AR1A, AR2 NM1A, NM4, NM5, NM6	CWD Survey (Vessel)				AR1A, AR2		
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM		
		mid-ebb: 18:31		mid-ebb: 08:47		mid-ebb: 10:42		
14	15	mid-flood: 12:01	17	mid-flood: 15:01	19	mid-flood: 17:45 20		
17	19	Site Inspection	Site Inspection	Site Inspection	Site Inspection	20		
		CWD Survey (Land-based, Vessel)	CWD Survey (Vessel)	CWD Survey (Vessel)	AR1A, AR2			
					NM1A, NM4, NM5, NM6			
		WQ General & Regular DCM mid-ebb: 12:48		WQ General & Regular DCM mid-ebb: 14:04		WQ General & Regular DCM mid-ebb: 15:12		
		mid-flood: 12.46		mid-flood: 07:01		mid-flood: 08:17		
21	22	23	24	25	26	27		
	CWD Survey (Vessel)	Site Inspection CWD Survey (Vessel)	Site Inspection CWD Survey (Vessel)	Site Inspection CWD Survey (Land-based)	Site Inspection CWD Survey (Land-based)			
			, (,	AR1A, AR2				
				NM1A, NM4, NM5, NM6				
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM		
		mid-ebb: 16:53 mid-flood: 10:26		mid-ebb: 18:30 mid-flood: 12:41		mid-ebb: 09:08 mid-flood: 15:45		
28	29	30	31	Tarre		10.10		
		Site Inspection	Site Inspection					
		WQ General & Regular DCM						
		mid-ebb: 11:37						
		mid-flood: 18:49 Notes:						
		CWD - Chinese White Dolphin	MM44/4D44 M. T. D. := :					
		Air quality and Noise Monitoring Station	NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon F NM5/AR2 - Village House, Tin Sum					
			NM6 - House No. 1, Sha Lo Wan					
		WQ - Water Quality DCM - Deep Cement Mixing						
		2550 55115111 11111111111111111111111111						
		*Air quality moniotring at AR2 was resch	eduled from 2 July 2019 to 3 July 201	9 due to malfunction of monitoring equipmen	t.			
	*Air quality moniotring at AR2 was rescheduled from 2 July 2019 to 3 July 2019 due to malfunction of monitoring equipment.							

Tentative Monitoring Schedule of Next Reporting Period

Aug-19

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Sullday	Monday	Tuesday	weunesuay			
				1	2	3
				Site Inspection	Site Inspection	
					AR1A, AR2*	
					NM1A, NM4, NM5, NM6	
				WQ General & Regular DCM		WQ General & Regular DCM
				mid-ebb: 13:11 mid-flood: 20:18		mid-ebb: 14:43 mid-flood: 07:49
4	5	6	7	8	9	10
4	3		Site Inspection	Site Inspection	Site Inspection	10
		Site Inspection CWD Survey (Land-based)	CWD Survey (Vessel)	CWD Survey (Vessel)	CWD Survey (Vessel)	
		AR1A, AR2	OVV D Curvey (VCSSCI)	OVV D Gui Vey (Vessei)	OVVD Curvey (Vessel)	
		NM1A, NM4, NM5, NM6				
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM
		mid-ebb: 17:07 mid-flood: 10:37		mid-ebb: 06:59 mid-flood: 13:21		mid-ebb: 09:26 mid-flood: 16:50
11	12	13	14	15	16	17
""	12	Site Inspection	Site Inspection	Site Inspection	Site Inspection	17
	CWD Survey (Vessel)	CWD Survey (Vessel)	Oile Hispection	CWD Survey (Land-based)	CWD Survey (Vessel)	
	AR1A, AR2			, (,	0112 02112) (10000)	AR1A, AR2
	NM1A, NM4, NM5, NM6					
		WQ General & Regular DCM mid-ebb: 11:53		WQ General & Regular DCM mid-ebb: 13:08		WQ General & Regular DCM mid-ebb: 14:15
		mid-flood: 04:48		mid-flood: 13.06		mid-flood: 07:29
18	19	20	21	22	23	24
		Site Inspection	Site Inspection	Site Inspection	Site Inspection	
	CWD Survey (Vessel)	CWD Survey (Land-based)	CWD Survey (Vessel)			
					AR1A, AR2	
					NM1A, NM4, NM5, NM6	
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM
		mid-ebb: 15:42		mid-ebb: 16:53		mid-ebb: 06:57
		mid-flood: 09:25		mid-flood: 11:03		mid-flood: 13:46
25	26	27	28	29	30	31
		Site Inspection	Site Inspection	Site Inspection	Site Inspection	
				AR1A, AR2 NM1A, NM4, NM5, NM6		
				MINITA, MINIA, MINIS, MINIO		
		WQ General & Regular DCM		WQ General & Regular DCM		WQ General & Regular DCM
		mid-ebb: 10:23		mid-ebb: 12:07		mid-ebb: 13:41
		mid-flood: 17:49		mid-flood: 19:11		mid-flood: 20:25
		Notes:				
		CMD Chinana Multi- Bullium				
		CWD - Chinese White Dolphin	NM1A/AR1A - Man Tung Road Park			
			NM4 - Ching Chung Hau Po Woon F			
		Air quality and Noise Monitoring Station	NM5/AR2 - Village House, Tin Sum	•		
			NM6 - House No. 1, Sha Lo Wan			
		WQ - Water Quality				
		DCM - Deep Cement Mixing				
		*Air quality monitoring at AR1A and AR2	was rescheduled from 31 July 2019	to 2 August 2019 due to Strong Wind Signal I	No. 3 in force.	
	•					