Appendix C. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Sep-22

Constant	Mandau	Torondore	300 ZZ		Faidon	Catumdan				
Sunday	Monday	Tuesday	Wednesday	Thursday	Friday 2	Saturday 3				
				1 '	Site Inspection	3				
					NM4, NM6					
				WQ General		WQ General				
				mid-ebb: 16:00		mid-ebb: 17:47				
4	5	6	7	mid-flood: 09:52	9	mid-flood: 12:18 10				
•	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection					
	CWD Survey (Vessel)	CWD Survey (Vessel)		CWD Survey (Vessel)	CWD Survey (Vessel)					
	, , , , , , , , , , , , , , , , , , , ,	AR1A, AR2		, , , , , , , , , , , , , , , , , , , ,		AR1A, AR2				
		NM1A, NM5			NM4, NM6					
		WQ General		WQ General		WQ General				
		mid-ebb: 09:1: mid-flood: 17:2:		mid-ebb: 11:23 mid-flood: 18:48		mid-ebb: 12:59 mid-flood: 19:53				
11	12	13	14	15	16	17				
		Site Inspection	Site Inspection	Site Inspection	Site Inspection					
			CWD Survey (Vessel)		CWD Survey (Land-based)					
				NM4, NM6	AR1A, AR2 NM1A, NM5					
					Turry, Turc					
		WQ General mid-ebb: 14:5	1	WQ General mid-ebb: 15:54		WQ General mid-ebb: 17:07				
		mid-flood: 08:3	9	mid-flood: 10:12	1	mid-flood: 12:28				
18	19	20	21	22	23	24				
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection					
	CWD Survey (Vessel)	CWD Survey (Vessel)	CWD Survey (Vessel, Land-based)	AR1A, AR2						
				NM1A, NM5	NM4, NM6					
		WQ General		WQ General		WQ General				
		mid-ebb: 09:0	1	mid-ebb: 11:00		mid-ebb: 12:16				
05		mid-flood: 21:4 27		mid-flood: 18:17 29		mid-flood: 18:56				
25	26 Site Inspection	Site Inspection	28 Site Inspection	Site Inspection	30 Site Inspection					
				3112 1112 2112						
			AR1A, AR2							
			NM1A, NM5		NM4, NM6 ^[1]					
		WQ General		WQ General						
		mid-ebb: 13:5		mid-ebb: 15:05						
		mid-flood: 07:3	9	mid-flood: 09:08						
		Notes: Contract Number - Site Inspection								
		CWD - Chinese White Dolphin								
		NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School								
		NM5/AR2 - Village House, Tin Sum								
		NM6 - House No. 1, Sha Lo Wan WQ - Water Quality								
		[1] Noise monitoring sessions for NM4 & NM6 were rescheduled from 30 September 2022 to 5 October 2022 due to the hoisting of Amber Rainstorm Signal.								

Tentative Monitoring Schedule of Next Reporting Period

Oct-22

Constant	Mandau	Tuesday	Madaaadaa		Estatoria	Q-tl
Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
						1
						WQ General
						mid-ebb: 16:40 mid-flood: 11:13
2	3	4	5	6	7	8
_	Site Inspection		Site Inspection	Site Inspection		
	CWD Survey (Vessel)			CWD Survey (Ves	cwD Survey (Vessel)	
	AR1A, AR2			CWD Survey (ves	CVVD Survey (Vessel)	AR1A, AR2
	NM1A, NM5		NM4, NM6 ^[1]		NM4, NM6	
		WQ General		WQ General		WQ General
		mid-ebb: 07:23		mid-ebb:	10:12	mid-ebb: 11:54
		mid-flood: 20:21		mid-flood:	17:42	mid-flood: 18:41
9	10	11	12	13	14	15
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection	
	CWD Survey (Vessel)	CWD Survey (Vessel)		CWD Survey (Ves		
				NM4, NM6	AR1A, AR2 NM1A, NM5	
				NIVI4, NIVI6	NIVITA, NIVIS	
		WQ General		WQ General		WQ General
		mid-ebb: 13:48 mid-flood: 07:48		mid-ebb: mid-flood:	14:54 09:19	mid-ebb: 16:00 mid-flood: 11:05
16	17	18	19	20	21	22
	Site Inspection	Site Inspection	Site Inspection	Site Inspection		
	CWD Survey (Land-based)		CWD Survey (Vessel)			
	CWD Survey (Land-based)		CWD Survey (Vessel)	AR1A, AR2		
				NM1A, NM5	NM4, NM6	
		WQ General		WQ General		WQ General
		mid-ebb: 06:20		mid-ebb:	09:14	mid-ebb: 11:00
		mid-flood: 19:11		mid-flood:	17:10	mid-flood: 17:42
23	24	25	26 Site Inspection	27	28	29
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection	
	CWD Survey (Land-based)					
			AR1A, AR2 NM1A, NM5		NM4, NM6	
			THITT, THIS		THIFF, THIO	
		WQ General		WQ General		WQ General
		mid-ebb: 12:52 mid-flood: 06:51		mid-ebb: mid-flood:	14:13 08:26	mid-ebb: 15:44 mid-flood: 10:20
30	31	Notes:				10120
	Site Inspection					
		CWD - Chinese White Dolphin	NM1A/AR1A - Man Tung Road Park			
		Air quality and Naise Manitorin - Ct-ti	NM4 - Ching Chung Hau Po Woon Prin	nary School		
		Air quality and Noise Monitoring Station	NM5/AR2 - Village House, Tin Sum	•		
		WQ - Water Quality	NM6 - House No. 1, Sha Lo Wan			
		[1] Noise monitoring sessions for NM4 & N	NM6 were rescheduled from 30 Septemb	er 2022 to 5 October 2022 due to th	ne hoisting of Amber Rainstorm Signal.	
		-				