

Appendix B. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Jun-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
		1 Site Inspection NM4, NM6 WQ General & Regular DCM mid-ebb: 17:46 mid-flood: 10:29	2 Site Inspection	3 Site Inspection AR1A, AR2 NM1A, NM5 WQ General & Regular DCM mid-ebb: 8:48 mid-flood: 13:31	4 Site Inspection CWD Survey (Vessel)	5 WQ General & Regular DCM mid-ebb: 10:25 mid-flood: 16:02
6	7 Site Inspection CWD Survey (Vessel)	8 Site Inspection CWD Survey (Vessel) WQ General & Regular DCM mid-ebb: 12:05 mid-flood: 5:19	9 Site Inspection CWD Survey (Land-based) AR1A, AR2 NM1A, NM5	10 Site Inspection WQ General & Regular DCM mid-ebb: 13:08 mid-flood: 6:07	11 Site Inspection NM4, NM6	12 WQ General & Regular DCM mid-ebb: 14:16 mid-flood: 7:03
13	14	15 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General & Regular DCM mid-ebb: 16:13 mid-flood: 8:50	16 Site Inspection CWD Survey (Land-based)	17 Site Inspection CWD Survey (Vessel) NM4, NM6 WQ General & Regular DCM mid-ebb: 17:50 mid-flood: 10:38	18 Site Inspection	19 WQ General & Regular DCM mid-ebb: 8:20 mid-flood: 13:46
20	21 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	22 Site Inspection CWD Survey (Vessel) WQ General & Regular DCM mid-ebb: 10:56 mid-flood: 4:15	23 Site Inspection	24 Site Inspection NM4, NM6 WQ General mid-ebb: 12:34 mid-flood: 5:36	25 Site Inspection CWD Survey (Vessel)	26 AR1A, AR2 WQ General mid-ebb: 14:10 mid-flood: 7:02
27	28 Site Inspection	29 Site Inspection WQ General mid-ebb: 16:30 mid-flood: 9:25	30 Site Inspection NM4, NM6			
Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality DCM - Deep Cement Mixing NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan						

Tentative Monitoring Schedule of Next Reporting Period

Jul-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				1 WQ General mid-ebb: 18:04 mid-flood: 11:27	2 Site Inspection AR1A, AR2 NM1A, NM5	3 WQ General mid-ebb: 8:44 mid-flood: 14:06
4	5 Site Inspection NM4, NM6	6 Site Inspection WQ General mid-ebb: 11:04 mid-flood: 17:50	7	8 Site Inspection AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 12:14 mid-flood: 19:23	9 Site Inspection	10 WQ General mid-ebb: 13:25 mid-flood: 20:38
11	12 Site Inspection CWD Survey (Vessel, Land-based)	13 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 15:18 mid-flood: 8:10	14 CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	15 Site Inspection NM4, NM6 WQ General mid-ebb: 16:39 mid-flood: 9:44	16 Site Inspection	17 WQ General mid-ebb: 18:19 mid-flood: 11:54
18	19 Site Inspection CWD Survey (Vessel) NM4, NM6	20 Site Inspection CWD Survey (Land-based) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 9:40 mid-flood: 16:50	21 CWD Survey (Vessel)	22 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 11:33 mid-flood: 19:02	23 Site Inspection	24 WQ General mid-ebb: 13:12 mid-flood: 20:34
25	26 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	27 Site Inspection NM4, NM6 WQ General mid-ebb: 15:23 mid-flood: 8:29	28 CWD Survey (Vessel)	29 Site Inspection WQ General mid-ebb: 16:36 mid-flood: 10:03	30 Site Inspection	31 WQ General mid-ebb: 17:47 mid-flood: 11:56
Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan						