

Appendix B. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Dec-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1 CWD Survey (Vessel)	2 Site Inspection WQ General mid-ebb: 11:13 mid-flood: 17:03	3 Site Inspection CWD Survey (Vessel)	4 AR1A, AR2 WQ General mid-ebb: 13:00 mid-flood: 07:26
5	6 Site Inspection CWD Survey (Vessel)	7 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 15:24 mid-flood: 10:14	8 Site Inspection	9 Site Inspection NM4, NM6 WQ General mid-ebb: 17:40 mid-flood: 12:35	10 Site Inspection AR1A, AR2 NM1A, NM5	11 WQ General mid-ebb: 20:24 mid-flood: 14:26
12	13 Site Inspection CWD Survey (Vessel)	14 Site Inspection NM4, NM6 WQ General mid-ebb: 09:38 mid-flood: 16:10	15 CWD Survey (Vessel)	16 Site Inspection CWD Survey (Vessel, Land-based) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 11:18 mid-flood: 16:57	17 Site Inspection CWD Survey (Vessel)	18 WQ General mid-ebb: 12:35 mid-flood: 07:29
19	20 Site Inspection CWD Survey (Land-based)	21 Site Inspection WQ General mid-ebb: 14:11 mid-flood: 09:21	22 Site Inspection AR1A, AR2 NM1A, NM5	23 Site Inspection NM4, NM6 WQ General mid-ebb: 15:23 mid-flood: 10:37	24 Site Inspection	25 WQ General mid-ebb: 17:07 mid-flood: 12:05
26	27	28 Site Inspection AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 07:02 mid-flood: 14:20	29 Site Inspection NM4, NM6	30 Site Inspection WQ General mid-ebb: 09:51 mid-flood: 15:39	31 Site Inspection	
Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan						

Tentative Monitoring Schedule of Next Reporting Period

Jan-22

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
						1 WQ General mid-ebb: 12:02 mid-flood: 17:04
2	3 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	4 Site Inspection CWD Survey (Vessel) NM4, NM6 WQ General mid-ebb: 14:27 mid-flood: 09:15	5 Site Inspection CWD Survey (Vessel)	6 Site Inspection WQ General mid-ebb: 16:01 mid-flood: 10:45	7 Site Inspection	8 AR1A, AR2 WQ General mid-ebb: 17:54 mid-flood: 12:16
9	10 Site Inspection CWD Survey (Vessel)	11 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 07:07 mid-flood: 14:19	12 CWD Survey (Vessel)	13 Site Inspection NM4, NM6 WQ General mid-ebb: 09:54 mid-flood: 15:18	14 Site Inspection AR1A, AR2 NM1A, NM5	15 WQ General mid-ebb: 11:39 mid-flood: 06:57
16	17 Site Inspection CWD Survey (Land-based)	18 Site Inspection NM4, NM6 WQ General mid-ebb: 13:27 mid-flood: 08:31	19 CWD Survey (Vessel)	20 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 14:37 mid-flood: 09:31	21 Site Inspection	22 WQ General mid-ebb: 15:55 mid-flood: 10:33
23	24 Site Inspection CWD Survey (Land-based)	25 Site Inspection NM4, NM6 WQ General mid-ebb: 05:25 mid-flood: 12:21	26 AR1A, AR2 NM1A, NM5	27 Site Inspection WQ General mid-ebb: 08:03 mid-flood: 13:53	28 Site Inspection	29 WQ General mid-ebb: 11:04 mid-flood: 15:49
30	31 Site Inspection AR1A, AR2 NM1A, NM5	Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan				