


Appendix B Representative Photographs taken during the Dive Survey



Artificial Sloping Seawall with Boulders



Typical Substratum Surface



Guaigorgia sp. at Survey Station D5




Soft coral at Survey Station D6



Soft coral at Survey Station D7



Soft coral at Survey Station D8



Paracyathus rotundatus at Survey Station D6



Paracyathus rotundatus at Survey Station D7



Rocky coastline at Sha Chau (Survey Station D9)



Guaiaigorgia sp. with partial mortality at Survey Station D9