

Appendix C. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Sep-16

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				1 CWD Land-based Survey WQ General & Regular DCM mid-ebb: 13:06 mid-flood: 06:27	2	3 WQ General & Regular DCM mid-ebb: 14:15 mid-flood: 07:46
4	5 AR1A NM6 CWD Vessel Survey	6 NM4 NM1A NM5/AR2 NM3A CWD Vessel Survey WQ General & Regular DCM mid-ebb: 15:47 mid-flood: 09:42	7 CWD Land-based Survey	8 Site Inspection CWD Vessel Survey WQ General & Regular DCM mid-ebb: 17:05 mid-flood: 11:24	9 AR1A	10 WQ General & Regular DCM mid-ebb: 07:00 mid-flood: 14:58
11	12 Site Inspection NM5/AR2 NM3A NM6	13 CWD Land-based Survey WQ General & Regular DCM mid-ebb: 10:21 mid-flood: 17:40	14 Site Inspection	15 NM1A/AR1A NM4 AR2 WQ General & Regular DCM mid-ebb: 11:51 mid-flood: 18:40	16	17 WQ General & Regular DCM mid-ebb: 13:12 mid-flood: 06:50
18	19 Site Inspection NM5/AR2 CWD Vessel Survey	20 CWD Vessel Survey WQ General & Regular DCM mid-ebb: 15:20 mid-flood: 09:22	21 Site Inspection NM1A/AR1A NM4 NM3A	22 NM6 CWD Vessel Survey WQ General & Regular DCM mid-ebb: 17:07 mid-flood: 11:35	23 AR2 CWD Land-based Survey	24 WQ General & Regular DCM mid-ebb: 06:51 mid-flood: 14:46
25	26 Site Inspection NM6 CWD Vessel Survey CWD Land-based Survey	27 NM1A/AR1A NM4 NM3A CWD Vessel Survey WQ General & Regular DCM mid-ebb: 10:38 mid-flood: 17:39	28	29 NM5/AR2 WQ General & Regular DCM mid-ebb: 12:05 mid-flood: 18:33	30 Site Inspection Ecological Monitoring	
Notes: NM1A/AR1A - Man Tung Road Park NM3A - Site Office Air quality and Noise monitoring Station NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan CWD - Chinese White Dolphin WQ - Water Quality DCM - Deep Cement Mixing						

Tentative Monitoring Schedule of Next Reporting Period

OCTOBER 2016

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
						1 WQ General & Regular DCM mid-ebb: 13:16 mid-flood: 07:01
2	3 Site Inspection NM1A/AR1A NM4 NM3A	4 CWD Land-based Survey WQ General & Regular DCM mid-ebb: 14:49 mid-flood: 08:52	5 Site Inspection NM5/AR2 CWD Vessel Survey	6 Site Inspection NM6 CWD Land-based Survey WQ General & Regular DCM mid-ebb: 10:30 mid-flood: 17:24	7 Site Inspection AR1A CWD Vessel Survey	8 WQ General & Regular DCM mid-ebb: 17:44 mid-flood: 12:40
9	10	11 Site Inspection NM5/AR2 CWD Vessel Survey CWD Land-based Survey WQ General & Regular DCM mid-ebb: 08:32 mid-flood: 16:18	12 Site Inspection CWD Vessel Survey CWD Land-based Survey	13 Site Inspection NM1A/AR1A NM4 NM3A NM6 WQ General & Regular DCM mid-ebb: 10:30 mid-flood: 17:24	14 Site Inspection	15 WQ General & Regular DCM mid-ebb: 12:04 mid-flood: 18:22
16	17 Site Inspection NM5/AR2	18 NM6 CWD Vessel Survey WQ General & Regular DCM mid-ebb: 14:21 mid-flood: 08:29	19 Site Inspection Ecological Monitoring NM1A/AR1A NM4 NM3A CWD Vessel Survey	20 Site Inspection CWD Land-based Survey WQ General & Regular DCM mid-ebb: 16:02 mid-flood: 10:30	21 Site Inspection AR2	22 WQ General & Regular DCM mid-ebb: 18:05 mid-flood: 12:51
23	24 Site Inspection NM6	25 NM1A/AR1A NM4 NM3A CWD Vessel Survey WQ General & Regular DCM mid-ebb: 09:10 mid-flood: 16:25	26 Site Inspection CWD Vessel Survey	27 Site Inspection NM5/AR2 WQ General & Regular DCM mid-ebb: 10:57 mid-flood: 17:25	28 Site Inspection	29 WQ General & Regular DCM mid-ebb: 12:16 mid-flood: 18:12
30	31 Site Inspection	Notes: Air quality and Noise monitoring Station CWD - Chinese White Dolphin WQ - Water Quality DCM - Deep Cement Mixing NM1A/AR1A - Man Tung Road Park NM3A - Site Office NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan				