

## **Appendix C. Monitoring Schedule**

# **Monitoring Schedule of This Reporting Period**

# Jul-18

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<b>1</b>	<b>2</b>	<b>3</b> Site Inspection AR1A, AR2 NM1A, NM3A, NM4, NM5 WQ General & Regular DCM mid-ebb: 16:09 mid-flood: 9:16	<b>4</b> Site Inspection	<b>5</b> Site Inspection CWD Survey (Vessel) NM6 WQ General & Regular DCM mid-ebb: 17:32 mid-flood: 11:00	<b>6</b> Site Inspection AR1A, AR2	<b>7</b> WQ General & Regular DCM mid-ebb: 19:34 mid-flood: 13:40
<b>8</b>	<b>9</b> Site Inspection CWD Survey (Vessel)	<b>10</b> Site Inspection WQ General & Regular DCM mid-ebb: 10:44 mid-flood: 17:29	<b>11</b> Site Inspection CWD Survey (Vessel, Land-based)	<b>12</b> Site Inspection CWD Survey (Land-based) AR1A, AR2 NM1A, NM3A, NM4, NM5, NM6 WQ General & Regular DCM mid-ebb: 12:19 mid-flood: 19:26	<b>13</b> Site Inspection	<b>14</b> WQ General & Regular DCM* mid-ebb: 13:55 mid-flood: 21:04
<b>15</b>	<b>16</b> NM6	<b>17</b> Site Inspection CWD Survey (Vessel) WQ General & Regular DCM mid-ebb: 16:21 mid-flood: 9:29	<b>18</b> AR1A, AR2 NM1A, NM3A, NM4, NM5	<b>19</b> Site Inspection CWD Survey (Vessel, Land-based) WQ General & Regular DCM mid-ebb: 18:07 mid-flood: 11:41	<b>20</b> Site Inspection CWD Survey (Vessel, Land-based)	<b>21</b> WQ General & Regular DCM mid-ebb: 20:23 mid-flood: 14:36
<b>22</b>	<b>23</b>	<b>24</b> Site Inspection AR1A, AR2 NM1A, NM3A, NM4, NM5 WQ General & Regular DCM mid-ebb: 11:07 mid-flood: 18:19	<b>25</b> Site Inspection	<b>26</b> Site Inspection CWD Survey (Vessel, Land-based) NM6 WQ General & Regular DCM mid-ebb: 12:22 mid-flood: 19:33	<b>27</b> Site Inspection	<b>28</b> WQ General & Regular DCM mid-ebb: 13:32 mid-flood: 20:37
<b>29</b>	<b>30</b> CWD Survey (Vessel) AR1A, AR2 NM1A, NM3A, NM4, NM5	<b>31</b> Site Inspection WQ General & Regular DCM mid-ebb: 15:08 mid-flood: 8:26				
<p><b>Notes:</b>            Contract Number - Site Inspection            CWD - Chinese White Dolphin            NM1A/AR1A - Man Tung Road Park            NM3A - Site Office            Air quality and Noise Monitoring Station            NM4 - Ching Chung Hau Po Woon Primary School            NM5/AR2 - Village House, Tin Sum            NM6 - House No. 1, Sha Lo Wan            WQ - Water Quality            DCM - Deep Cement Mixing            * WQ monitoring session on 14 July 2018 was cancelled due to adverse weather.</p>						

# **Tentative Monitoring Schedule of Next Reporting Period**

# Aug-18

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			<b>1</b> Site Inspection CWD Survey (Land-based) NM6	<b>2</b> Site Inspection CWD Survey (Vessel, Land-based) WQ General & Regular DCM mid-ebb: 16:16 mid-flood: 09:51	<b>3</b> Site Inspection AR1A, AR2	<b>4</b> WQ General & Regular DCM mid-ebb: 17:45 mid-flood: 11:50
<b>5</b>	<b>6</b> CWD Survey (Land-based)	<b>7</b> Site Inspection CWD Survey (Vessel) NM6 WQ General & Regular DCM mid-ebb: 15:14 mid-flood: 08:31	<b>8</b> Site Inspection	<b>9</b> Site Inspection CWD Survey (Land-based) AR1A, AR2 NM1A, NM3A, NM4, NM5 Ecological Monitoring WQ General & Regular DCM mid-ebb: 11:13 mid-flood: 18:26	<b>10</b> Site Inspection	<b>11</b> WQ General & Regular DCM mid-ebb: 12:54 mid-flood: 19:58
<b>12</b>	<b>13</b> CWD Survey (Land-based) NM6	<b>14</b> Site Inspection CWD Survey (Vessel) WQ General & Regular DCM mid-ebb: 09:51 mid-flood: 17:28	<b>15</b> Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM3A, NM4, NM5	<b>16</b> Site Inspection CWD Survey (Vessel) WQ General & Regular DCM mid-ebb: 16:41 mid-flood: 10:17	<b>17</b> Site Inspection CWD Survey (Vessel)	<b>18</b> WQ General & Regular DCM mid-ebb: 18:26 mid-flood: 12:41
<b>19</b>	<b>20</b> CWD Survey (Vessel)	<b>21</b> Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM3A, NM4, NM5 WQ General & Regular DCM mid-ebb: 11:07 mid-flood: 18:19	<b>22</b> Site Inspection	<b>23</b> Site Inspection NM6 WQ General & Regular DCM mid-ebb: 12:22 mid-flood: 19:33	<b>24</b> Site Inspection	<b>25</b> WQ General & Regular DCM mid-ebb: 12:35 mid-flood: 19:36
<b>26</b>	<b>27</b> AR1A, AR2 NM1A, NM3A, NM4, NM5	<b>28</b> Site Inspection WQ General & Regular DCM mid-ebb: 14:10 mid-flood: 07:38	<b>29</b> Site Inspection NM6	<b>30</b> Site Inspection WQ General & Regular DCM mid-ebb: 15:13 mid-flood: 08:58	<b>31</b> Site Inspection AR1A, AR2	
<b>Notes:</b> CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality DCM - Deep Cement Mixing NM1A/AR1A - Man Tung Road Park NM3A - Site Office NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan						