

Appendix B. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Jul-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				1 WQ General mid-ebb: 18:04 mid-flood: 11:27	2 Site Inspection AR1A, AR2 NM1A, NM5	3 WQ General mid-ebb: 8:44 mid-flood: 14:06
4	5 Site Inspection NM4, NM6	6 Site Inspection WQ General mid-ebb: 11:04 mid-flood: 17:50	7	8 Site Inspection AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 12:14 mid-flood: 19:23	9 Site Inspection	10 WQ General mid-ebb: 13:25 mid-flood: 20:38
11	12 Site Inspection CWD Survey (Vessel, Land-based)	13 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 15:18 mid-flood: 8:10	14 CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	15 Site Inspection NM4, NM6 WQ General mid-ebb: 16:39 mid-flood: 9:44	16 Site Inspection	17 WQ General mid-ebb: 18:19 mid-flood: 11:54
18	19 Site Inspection CWD Survey (Vessel) NM4, NM6	20 Site Inspection AR1A, AR2 NM1A, NM5 WQ General ⁽¹⁾ mid-ebb: 9:40 mid-flood: 16:50	21 CWD Survey (Vessel)	22 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 11:33 mid-flood: 19:02	23 Site Inspection	24 WQ General mid-ebb: 13:12 mid-flood: 20:34
25	26 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	27 Site Inspection CWD Survey (Land-based) NM4, NM6 WQ General mid-ebb: 15:23 mid-flood: 8:29	28 Site Inspection CWD Survey (Vessel)	29 Site Inspection WQ General mid-ebb: 16:36 mid-flood: 10:03	30 Site Inspection	31 AR1A, AR2 WQ General mid-ebb: 17:47 mid-flood: 11:56
Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality ⁽¹⁾ Water quality monitoring session on 20 July 2021 was cancelled due to Strong Wind Signal No.3 in force. NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan						

Tentative Monitoring Schedule of Next Reporting Period

Aug-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2 Site Inspection	3 Site Inspection WQ General mid-ebb: 9:40 mid-flood: 22:01	4	5 Site Inspection NM4, NM6 WQ General mid-ebb: 11:11 mid-flood: 18:36	6 Site Inspection AR1A, AR2 NM1A, NM5	7 WQ General mid-ebb: 12:29 mid-flood: 19:41
8	9 Site Inspection	10 Site Inspection WQ General mid-ebb: 14:22 mid-flood: 7:26	11 CWD Survey (Vessel) NM4, NM6	12 Site Inspection CWD Survey (Land-based) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 15:35 mid-flood: 8:56	13 Site Inspection	14 WQ General mid-ebb: 16:57 mid-flood: 10:40
15	16 Site Inspection CWD Survey (Vessel)	17 Site Inspection NM4, NM6 WQ General mid-ebb: 8:03 mid-flood: 15:44	18 CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	19 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 10:29 mid-flood: 18:13	20 Site Inspection CWD Survey (Vessel)	21 WQ General mid-ebb: 12:14 mid-flood: 19:35
22	23 Site Inspection CWD Survey (Vessel, Land-based) NM4, NM6	24 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 14:20 mid-flood: 7:37	25 Site Inspection CWD Survey (Vessel)	26 Site Inspection WQ General mid-ebb: 15:23 mid-flood: 9:02	27 Site Inspection	28 WQ General mid-ebb: 16:23 mid-flood: 10:31
29	30 Site Inspection AR1A, AR2 NM1A, NM5	31 Site Inspection NM4, NM6 WQ General mid-ebb: 7:20 mid-flood: 19:53				
<p>Notes:</p> <p>CWD - Chinese White Dolphin</p> <p>Air quality and Noise Monitoring Station</p> <p>WQ - Water Quality</p> <p>NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan</p>						