

Appendix B. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Aug-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2 Site Inspection	3 Site Inspection WQ General ⁽¹⁾ mid-ebb: 9:40 mid-flood: 22:01	4 Site Inspection	5 Site Inspection NM4, NM6 WQ General mid-ebb: 11:11 mid-flood: 18:36	6 Site Inspection AR1A, AR2 NM1A, NM5	7 WQ General mid-ebb: 12:29 mid-flood: 19:41
8	9 Site Inspection	10 Site Inspection WQ General mid-ebb: 14:22 mid-flood: 7:26	11 CWD Survey (Vessel) NM4, NM6	12 Site Inspection AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 15:35 mid-flood: 8:56	13 Site Inspection CWD Survey (Land-based)	14 WQ General mid-ebb: 16:57 mid-flood: 10:40
15	16 Site Inspection CWD Survey (Vessel)	17 Site Inspection NM4, NM6 WQ General mid-ebb: 8:03 mid-flood: 15:44	18 CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	19 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 10:29 mid-flood: 18:13	20 Site Inspection CWD Survey (Vessel)	21 WQ General mid-ebb: 12:14 mid-flood: 19:35
22	23 Site Inspection CWD Survey (Land-based) NM4, NM6	24 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 14:20 mid-flood: 7:37	25 Site Inspection CWD Survey (Vessel)	26 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 15:23 mid-flood: 9:02	27 Site Inspection	28 WQ General mid-ebb: 16:23 mid-flood: 10:31
29	30 Site Inspection AR1A, AR2 NM1A, NM5	31 Site Inspection NM4, NM6 WQ General mid-ebb: 7:20 mid-flood: 19:53				
<p>Notes:</p> <p>CWD - Chinese White Dolphin</p> <p>Air quality and Noise Monitoring Station</p> <p>WQ - Water Quality</p> <p>⁽¹⁾ Water quality monitoring session during mid flood tide on 3 August 2021 was cancelled due to Strong Wind Signal No.3 in force.</p> <p>NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan</p>						

Tentative Monitoring Schedule of Next Reporting Period

Sep-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1 Site Inspection	2 Site Inspection WQ General mid-ebb: 9:42 mid-flood: 22:15	3 Site Inspection CWD Survey (Land-based)	4 AR1A, AR2 WQ General mid-ebb: 11:23 mid-flood: 18:40
5	6 Site Inspection CWD Survey (Vessel)	7 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 13:22 mid-flood: 6:37	8 CWD Survey (Vessel) NM4, NM6	9 Site Inspection CWD Survey (Land-based) WQ General mid-ebb: 14:34 mid-flood: 8:08	10 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	11 WQ General mid-ebb: 15:53 mid-flood: 9:47
12	13 Site Inspection	14 Site Inspection WQ General mid-ebb: 6:13 mid-flood: 18:47	15 NM4, NM6	16 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 9:08 mid-flood: 17:19	17 Site Inspection CWD Survey (Vessel)	18 WQ General mid-ebb: 11:14 mid-flood: 18:34
19	20 Site Inspection CWD Survey (Vessel) NM4, NM6	21 Site Inspection AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 13:17 mid-flood: 6:49	22	23 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 14:20 mid-flood: 8:11	24 Site Inspection	25 WQ General mid-ebb: 15:18 mid-flood: 9:32
26	27 Site Inspection AR1A, AR2 NM1A, NM5	28 Site Inspection NM4, NM6 WQ General mid-ebb: 5:05 mid-flood: 17:21	29	30 Site Inspection WQ General mid-ebb: 7:15 mid-flood: 20:16		
<p>Notes:</p> <p>CWD - Chinese White Dolphin</p> <p>Air quality and Noise Monitoring Station</p> <p>WQ - Water Quality</p> <p>NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan</p>						