

Appendix C. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Sep-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1 Site Inspection	2 Site Inspection WQ General mid-ebb: 9:42 mid-flood: 22:15	3 Site Inspection CWD Survey (Land-based)	4 AR1A, AR2 WQ General mid-ebb: 11:23 mid-flood: 18:40
5	6 Site Inspection CWD Survey (Vessel)	7 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 13:22 mid-flood: 6:37	8 CWD Survey (Vessel) NM4, NM6	9 Site Inspection CWD Survey (Land-based) WQ General mid-ebb: 14:34 mid-flood: 8:08	10 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	11 WQ General mid-ebb: 15:53 mid-flood: 9:47
12	13 Site Inspection	14 Site Inspection WQ General mid-ebb: 6:13 mid-flood: 18:47	15 NM4, NM6	16 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 9:08 mid-flood: 17:19	17 Site Inspection CWD Survey (Vessel)	18 WQ General mid-ebb: 11:14 mid-flood: 18:34
19	20 Site Inspection CWD Survey (Vessel) NM4, NM6	21 Site Inspection AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 13:17 mid-flood: 6:49	22	23 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 14:20 mid-flood: 8:11	24 Site Inspection	25 WQ General mid-ebb: 15:18 mid-flood: 9:32
26	27 Site Inspection AR1A, AR2 NM1A, NM5	28 Site Inspection NM4, NM6 WQ General mid-ebb: 5:05 mid-flood: 17:21	29	30 Site Inspection WQ General mid-ebb: 7:15 mid-flood: 20:16		
Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan						

Tentative Monitoring Schedule of Next Reporting Period

Oct-21

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
					1	2 AR1A, AR2 WQ General mid-ebb: 09:56 mid-flood: 17:33
3	4 Site Inspection	5 Site Inspection WQ General mid-ebb: 12:14 mid-flood: 05:43	6 CWD Survey (Vessel) NM4, NM6	7 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 13:32 mid-flood: 07:18	8 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	9 WQ General mid-ebb: 14:56 mid-flood: 09:01
10	11 Site Inspection	12 Site Inspection CWD Survey (Vessel, Land-based) NM4, NM6 WQ General mid-ebb: 04:48 mid-flood: 12:39	13 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	14 WQ General mid-ebb: 07:12 mid-flood: 20:11	15 Site Inspection CWD Survey (Vessel, Land-based)	16 WQ General mid-ebb: 10:00 mid-flood: 17:27
17	18 Site Inspection CWD Survey (Vessel) NM4, NM6	19 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 12:14 mid-flood: 06:00	20	21 Site Inspection WQ General mid-ebb: 13:19 mid-flood: 07:24	22 Site Inspection	23 WQ General mid-ebb: 14:21 mid-flood: 08:45
24	25 Site Inspection AR1A, AR2 NM1A, NM5	26 Site Inspection NM4, NM6 WQ General mid-ebb: 15:52 mid-flood: 11:08	27	28 Site Inspection WQ General mid-ebb: 05:12 mid-flood: 17:36	29 Site Inspection	30 AR1A, AR2 WQ General mid-ebb: 07:28 mid-flood: 16:21
31		Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan				