

Appendix B. Monitoring Schedule

Monitoring Schedule of This Reporting Period

Jan-23

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2	3 Site Inspection WQ General mid-ebb: 10:55 mid-flood: 16:09	4 Site Inspection AR1A, AR2 NM1A, NM5	5 Site Inspection WQ General mid-ebb: 12:17 mid-flood: 07:24	6 Site Inspection CWD Survey (Vessel) NM4, NM6 ^[1]	7 WQ General mid-ebb: 13:23 mid-flood: 08:33
8	9 Site Inspection CWD Survey (Vessel)	10 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 15:03 mid-flood: 10:05	11 Site Inspection CWD Survey (Land-based)	12 Site Inspection CWD Survey (Vessel) NM4, NM6 WQ General mid-ebb: 16:20 mid-flood: 11:06	13 Site Inspection CWD Survey (Vessel)	14 WQ General mid-ebb: 18:09 mid-flood: 12:16
15	16 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	17 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 08:33 mid-flood: 14:20	18 Site Inspection CWD Survey (Vessel)	19 Site Inspection CWD Survey (Land-based) NM4, NM6 WQ General mid-ebb: 11:14 mid-flood: 16:02	20 Site Inspection	21 AR1A, AR2 WQ General mid-ebb: 12:58 mid-flood: 07:49
22	23	24 WQ General mid-ebb: 15:15 mid-flood: 09:53	25	26 Site Inspection NM4, NM6 WQ General mid-ebb: 16:51 mid-flood: 11:09	27 Site Inspection AR1A, AR2 NM1A, NM5	28 WQ General mid-ebb: 18:51 mid-flood: 12:22
29	30 Site Inspection	31 Site Inspection WQ General mid-ebb: 22:23 mid-flood: 09:45				
<p>Notes:</p> <p>CWD - Chinese White Dolphin</p> <p>Air quality and Noise Monitoring Station</p> <p>WQ - Water Quality</p> <p>[1] Due to internal resources mobilization, the monitoring session (NM4 and NM6) was rescheduled from 5 January 2023 to 6 January 2023.</p> <p>NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan</p>						

Tentative Monitoring Schedule of Next Reporting Period

Feb-23

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1 Site Inspection	2 Site Inspection AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 23:48 mid-flood: 11:29	3 Site Inspection NM4, NM6	4 WQ General mid-ebb: 12:42 mid-flood: 07:46
5	6 Site Inspection	7 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 14:12 mid-flood: 08:58	8 CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	9 Site Inspection NM4, NM6 WQ General mid-ebb: 15:12 mid-flood: 09:40	10 Site Inspection	11 WQ General mid-ebb: 16:25 mid-flood: 10:28
12	13 Site Inspection CWD Survey (Vessel)	14 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5 WQ General mid-ebb: 06:07 mid-flood: 12:06	15 CWD Survey (Land-based)	16 Site Inspection CWD Survey (Land-based) NM4, NM6 WQ General mid-ebb: 22:09 mid-flood: 09:32	17 Site Inspection	18 WQ General mid-ebb: 00:04 mid-flood: 06:54
19	20 Site Inspection CWD Survey (Vessel) AR1A, AR2 NM1A, NM5	21 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 14:13 mid-flood: 08:41	22	23 Site Inspection NM4, NM6 WQ General mid-ebb: 15:31 mid-flood: 09:41	24 Site Inspection CWD Survey (Vessel)	25 AR1A, AR2 WQ General mid-ebb: 16:49 mid-flood: 10:23
26	27 Site Inspection	28 Site Inspection CWD Survey (Vessel) WQ General mid-ebb: 20:06 mid-flood: 07:08				
Notes: CWD - Chinese White Dolphin Air quality and Noise Monitoring Station WQ - Water Quality NM1A/AR1A - Man Tung Road Park NM4 - Ching Chung Hau Po Woon Primary School NM5/AR2 - Village House, Tin Sum NM6 - House No. 1, Sha Lo Wan						