#### Appendix B. Monitoring Schedule

## Impact Monitoring Schedule of This Reporting Period

### Sep-24

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2	3	4	5	6	7
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection	
	Cité inspection	Cité inspection	One mapedian	Oile inspection	Cité inspection	
	AR1A, AR2					AR1A, AR2
	NM1A, NM5					
8	9	10	11	12	13	14
6						14
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection	
	NM4, NM6 <sup>[1]</sup>			NM4, NM6	AR1A, AR2	
	,				NM1A, NM5	
15	16	17	18	19	20	21
	Site Inspection	Site Inspection		Site Inspection	Site Inspection	
	Cité inopedien	Cité inspection		Cité inspection	Cité inspection	
				AR1A, AR2	NM4, NM6	
				NM1A, NM5		
22	23	24	25	26	27	28
22						20
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection	
			1011 100		NII.44 NII.46	
			AR1A, AR2		NM4, NM6	
			NM1A, NM5			
29	30					
23						
	Site Inspection					
	AR1A, AR2					
	NM1A, NM5					
	,					
		Notes:				
		Site Inspection				
		NM1A/AR1A - Man Tung Road Park				
		Air quality and Noise Monitoring Station  NM4 - Ching Chung Hau Po Woon Primary School				
		Nivis/AR2 - Village House, Till Sulfi				
		NM6 - House No. 1, Sha Lo Wan  NM7 - House No. 1, Sha Lo Wan  NM7 - House No. 1, Sha Lo Wan  NM8 - House No. 1, Sha Lo Wan				
		[1] Due to the Tropical Cyclone Warning Signal No.8, the monitoring session (NM4 and NM6) was rescheduled from 6 September 2024 to 9 September 2024.				

## Tentative Impact Monitoring Schedule of Next Reporting Period

#### Oct-24

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Current	Monday	1	2	3	4	5
			Site Inspection	Site Inspection	Site Inspection	
					NIMA NIMO	AD4A AD0
					NM4, NM6	AR1A, AR2
	_			10		10
6	7	8 Cita Inanastian	9 Site Inspection	10	11	12
	Site Inspection	Site Inspection	Site Inspection	Site Inspection		
			NM4, NM6	AR1A, AR2		
				NM1A, NM5		
13	14	15	16	17	18	19
	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection	
			AR1A, AR2		NM4, NM6	
			NM1A, NM5		,	
20	21	22	23	24	25	26
20	Site Inspection	Site Inspection	Site Inspection	Site Inspection	Site Inspection	20
		1,111				
		AR1A, AR2			NM4, NM6	
		NM1A, NM5			,	
27	28	29	30	31		
21	Site Inspection	Site Inspection	Site Inspection	Site Inspection		
	Cité l'ispection	One inspection	One inspection	One inspection		
	AD44 AD0			NIMA NIMO		
	AR1A, AR2 NM1A, NM5			NM4, NM6		
		Notes				
		Notes:  Contract Number - Site Inspection				
		Contract Number - One hapetion				
		NM1A/AR1A - Man Tung Road Park Air quality and Noise Monitoring Station NM4 - Ching Chung Hau Po Woon Primary School				
		Air quality and Noise Monitoring Station	NM5/AR2 - Village House, Tin Sum	nary Concol		
			NM6 - House No. 1, Sha Lo Wan			

# Post-construction Phase CWD Monitoring Schedule of This Reporting Period

Sep-24

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2	3	4	5	6	7
•	-					•
		CWD Survey (Vessel)	CWD Survey (Vessel)			
		3112 32113) (13323)				
8	9	10	11	12	13	14
	CWD Survey (Vessel)	CWD Survey (Vessel)	CWD Survey (Vessel)			
15	16	17	18	19	20	21
				CWD Survey (Vessel)		
		0.4	05		0.7	00
22	23	24	25	26	27	28
		CWD Survey (Vessel)	CWD Survey (Vessel)			
		7.				
	100					
29	30					
		Notes:				
		CWD - Chinese White Dolphin				
		I				
		I				

# Tentative Post-construction Phase CWD Monitoring Schedule of Next Reporting Period

#### Oct-24

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
- Sanday		1	2	3	4	5
	_	_				
6	7	8	9	10	11	12
	CWD Survey (Vessel)	CWD Survey (Vessel)		CWD Survey (Vessel)		
13	14	15	16	17	18	19
		CWD Survey (Vessel)		CWD Survey (Vessel)	CWD Survey (Vessel)	
		CWD Survey (Vessel)		GWD Guivey (Vessel)	GWD Survey (Vessel)	
20	21	22	23	24	25	26
20	21	22	23	24	25	20
		OM/D Over the (Manual)	OMD Comment (Manager)			
		CWD Survey (Vessel)	CWD Survey (Vessel)			
				-		
27	28	29	30	31		
		Notes:				
		CWD - Chinese White Dolphin				